

11/05/2020

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM  
FEDERAL REGISTER REPORT FOR 11/06/2020

UNSUITABLE PROPERTIES

LAND

OREGON

Roadway Adjacent. to Ft. Stevens Cemetery

See Directions

Hammond OR

Landholding Agency: GSA

Property Number: 54202040004

Status: Excess

GSA Number: 10-D-OR-0817-AB

Directions:

A portion of the Russell Drive, Hammond, Oregon 97121. A strip of land contains 0.39 +/- acres. It is the access road adjacent to the Fort Stevens Cemetery.

Comments:

This is a roadway with no developable land or structures.

Reasons:

Inaccessible. Other - This is a roadway

UNSUITABLE PROPERTIES

BUILDING

FLORIDA

NWEC 605 Maintenance Shop

815 Oyster Bar Lane

Everglades FL 34139

Landholding Agency: DOI

Property Number: 61202040012

Status: Excess

Directions:

RPUID: 67295. Lat. 25.845533, Long. -081.387050

Comments:

53 yr. old wooden structure, 3,576 SF. Located on waterfront-periodic flooding. Structurally unsound. Mold and mildew present.

Reasons:

Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES  
BUILDING  
GEORGIA

Pumphouse on Leased Land  
1109 Experiment Street  
Griffin GA 30223-1797  
Landholding Agency: USDA  
Property Number: 15202040015  
Status: Underutilized  
Directions:

660700B015-PUMP HOUSE ON LSD LAND. RPUID: 21207054320.

Comments:

Extensive deterioration. Masonry construction-not suitable for offsite removal.

Reasons:

Structural Damage - Extensive Deterioration

TEXAS

DE Marina Store  
118 Diablo East Marina Rd.  
Del Rio TX 78840  
Landholding Agency: DOI  
Property Number: 61202040011  
Status: Excess  
Directions:

RPUID: 87585

Comments:

Extremely poor condition. Bldg. is falling down around itself. LBP AEHS Inc.  
Report 2020. Not suitable for offsite removal.

Reasons:

Structural Damage - Extensive Deterioration. Documented  
Deficiencies-Contamination

UNSUITABLE PROPERTIES  
BUILDING  
WASHINGTON

Mill C Restroom  
3211 Reservoir Road  
Walla Walla WA 99362  
Landholding Agency: USACE  
Property Number: 31202040009  
Status: Unutilized  
Comments:

Building underwater due to flooding. Offsite removal. Restroom-possible  
biohazard due to human waste.

Reasons:

Floodway. Structural Damage - Extensive Deterioration