

SUITABLE / AVAILABLE PROPERTIES

BUILDING

WYOMING

YCC0011

105 Snowey Mountain Road

Yellowstone Nat Park WY 82190

Landholding Agency: DOI

Property Number: 61202020001

Status: Excess

Comments:

Off-site removal only; 48+ yrs. old; 1,250 sq. ft.; mobile home; poor condition; roof and flooring needs to be replaced; vacant 6+ mos.; contact DOI for more information

---

Summary for SUITABLE / AVAILABLE

---

Total number of = 1

SUITABLE / UNAVAILABLE PROPERTIES

BUILDING

MASSACHUSETTS

Brockton Army Reserve Ctr.

124 Manley St.

Brockton MA 02301

Landholding Agency: GSA

Property Number: 54202010006

Status: Excess

GSA Number: MA-0942-AA

Comments:

Correction to posting on 3/20/2020. Property is unavailable due to continuing Federal need.

---

Summary for SUITABLE / UNAVAILABLE

---

Total number of = 1

## UNSUITABLE PROPERTIES

### BUILDING

#### OREGON

Peavy Cabin Toilet

Granite OR 96769

Landholding Agency: USDA

Property Number: 15202010062

Status: Excess

Directions:

2161.005421, Approximately 16.4 road miles NE of Grant

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Very poor condition. Off-site removal not feasible. Possible bio-hazard-human waste.

#### SOUTH CAROLINA

Wood Ferry Bathhouse Loop B

Union SC 29379

Landholding Agency: USDA

Property Number: 15202020002

Status: Underutilized

Directions:

Country road 12-574, Latitude: 34.70144, Longitude: 081.4512

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Not feasible for removal-cinder block/slab

Chattanooga River Cabin

119 Beaver Lane

Mountain Rest SC 29664

Landholding Agency: USDA

Property Number: 15202020003

Status: Unutilized

Directions:

Tract 0.282

Reasons:

Floodway

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Property located in floodplain, extensive deterioration; roof leaks; flooding; building unsafe; contamination; asbestos, mold; vermin; contains CFC;

## UNSUITABLE PROPERTIES

## BUILDING

## SOUTH CAROLINA

accessible by river

## Lick Fork Lake Bathhouse

Edgefield SC 29824

Landholding Agency: USDA

Property Number: 15202020004

Status: Underutilized

## Directions:

From the square in downtown Edgefield, travel south on Hwy. 23 for 8.3 miles. Bear left onto HWY. 230 and travel 4 miles. Left on Lick Fork Lake Road (S19-263) travel 1.9 miles. Entrance is on the right.

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Poor condition. Masonry construction-not feasible for offsite removal.

## Lick Fork Lake Pumphouse

Edgefield SC 29824

Landholding Agency: USDA

Property Number: 15202020005

Status: Underutilized

## Directions:

From the square in downtown Edgefield, travel south on HWY 23 for 8.3 miles. Bear left onto HWY 230 and travel 4 miles. Left on Lick Fork Lake Road S19-263. Travel 1.9 miles, entrance is on the right.

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Poor condition-extensive deterioration. Masonry-not feasible for offsite removal.

## Parsons Mtn. CG Bathhouse

454 Parson's Mtn. Road

Abbeville SC 29620

Landholding Agency: USDA

Property Number: 15202020006

Status: Underutilized

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Extensive deterioration. Construction-cinder block on slab-not feasible for offsite removal.

## UNSUITABLE PROPERTIES

## BUILDING

## SOUTH CAROLINA

Parsons Mtn. Former Pump House

454 Parsons Mtn. Road

Abbeville SC 20620

Landholding Agency: USDA

Property Number: 15202020007

Status: Underutilized

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Construction materials-concrete block/slab not feasible for offsite removal

Parsons Picnic Area Bath

454 Parson's Mtn. Road

Abbeville SC 29620

Landholding Agency: USDA

Property Number: 15202020008

Status: Underutilized

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Construction materials-concrete block/slab not feasible for offsite removal

Woods Ferry CG Pumphouse

Union SC 29379

Landholding Agency: USDA

Property Number: 15202020009

Status: Underutilized

Directions:

County Rd. 12-574, Latitude: 34.70144, Longitude: -81.4512

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Construction materials-concrete block/slab not feasible for offsite removal

Wood Ferry CG B

Union SC 29379

Landholding Agency: USDA

## UNSUITABLE PROPERTIES

### BUILDING

#### SOUTH CAROLINA

Property Number: 15202020010

Status: Underutilized

Directions:

Country Road 12-544, Latitude: 34.07144; Longitude: 081.4512

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Cinder block-not feasible for offsite removal.

#### WYOMING

Building 923

Yellowstone National Park

4 White Sulphur St.

Yellowstone Nat Park WY 82193

Landholding Agency: DOI

Property Number: 61202010019

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition, structural integrity-may collapse during removal.

Building 931

12 Soda Mountain Road

Yellowstone Nat Park WY 82000

Landholding Agency: DOI

Property Number: 61202010020

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition. Structure may collapse upon offsite removal.

Building 929

416 Wonderland Road

Yellowstone Nat Park WY 82199

Landholding Agency: DOI

Property Number: 61202010021

Status: Excess

Reasons:

## UNSUITABLE PROPERTIES

### BUILDING

#### WYOMING

Structural Damage - Extensive Deterioration

Comments:

Poor condition. Structure may collapse upon offsite removal.

Building 926

6 White Sulphur St

Yellowstone Nat Park WY 82196

Landholding Agency: DOI

Property Number: 61202010024

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition, structure may collapse on off site removal.

Building 925

5 Soda Mountain Road

Yellowstone Nat Park WY 82195

Landholding Agency: DOI

Property Number: 61202010025

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition, structural integrity may collapse for off site removal.

Building 924

3 Soda Mountain

Yellowstone Nat Park WY 82194

Landholding Agency: DOI

Property Number: 61202010026

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition; unstable for off site removal.

## UNSUITABLE PROPERTIES

## BUILDING

## WYOMING

Building 922  
2 White Sulphur St  
Yellowstone Nat Park WY  
Landholding Agency: DOI  
Property Number: 61202010027  
Status: Excess

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Poor condition, off-site removal - may lose structural integrity. Extensive repairs needed.

Building 921  
1 Soda Mountain Road  
Yellowstone Nat Park WY 82191  
Landholding Agency: DOI  
Property Number: 61202010028  
Status: Excess

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Poor condition; off-site removal only - may lose structural integrity. Extensive repairs needed.

Building 920  
8 White Sulphur Street  
Yellowstone Nat Park WY  
Landholding Agency: DOI  
Property Number: 61202010029  
Status: Excess

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Poor condition, off-site removal - may lose structural integrity. Extensive repairs needed.

Building 928  
7 Soda Mountain Road  
Yellowstone Nat Park WY 82196  
Landholding Agency: DOI

## UNSUITABLE PROPERTIES

## BUILDING

## WYOMING

Property Number: 61202010022

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition, structure may collapse upon off site removal

Building 927

11 Soda Mountain

Yellowstone Nat Park WY 82197

Landholding Agency: DOI

Property Number: 61202010023

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor conditions, structure may collapse upon off site removal.

## ARIZONA

Rattlesnake Flush Toilet 11204

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202010063

Status: Underutilized

Directions:

Latitude: 33.8684 Longitude -111.6032  
Cave Creek Ranger District, B 10 IWeb#011204

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition. Possible bio-hazard-human waste.

Rattlesnake Flush Toilet B10

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202010064

Status: Unutilized

Directions:

Tonto National Forest  
Latitude 33.8694; Longitude -111.6032  
IWeb 0011002

## UNSUITABLE PROPERTIES

### BUILDING

#### ARIZONA

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Located in floodway. Vault toilet - possible bio-hazard human waste.

#### Flush Toilet Yellow Cliffs

Tonto National Forest

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202010065

Status: Underutilized

Directions:

Latitude: 33.8684 Longitude -111.6032, IWeb 012601

Reasons:

Documented Deficiencies-Contamination

Comments:

Flush toilet - possible bio-hazard- human waste.

#### Valentine Ridge Vault Toilet 2

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202020001

Status: Excess

Directions:

IWEB 050902, Latitude: 34.243565, Longitude: -11079688

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Extensive deterioration. Not feasible for offsite removal.

#### 01103 Rattlesnake Toilet B9

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202020013

Status: Unutilized

Directions:

WEB 01101 Tonto National Forest, Cave Creek Ranger District. Latitude: 33.8684;  
Longitude: -111.6032

Reasons:

Structural Damage - Extensive Deterioration

Comments:

## UNSUITABLE PROPERTIES

## BUILDING

## ARIZONA

Poor condition. Poss. biohazard-human waste. Remote offsite removal

## SB Cove Flush Toilet N 011003

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202020014

Status: Excess

Directions:

Latitude: 33.8684 Longitude: -111.6157  
Cave Creek Ranger District, Tonto National Forest

Reasons:

Structural Damage - Extensive Deterioration  
Floodway

Comments:

Poor condition. Possible biohazard-human waste

## SB Cove Toilet N

Payson AZ 85541

Landholding Agency: USDA

Property Number: 15202020015

Status: Excess

Directions:

Latitude: 33.8684; Longitude -111.6157  
Cave Creek Ranger District, Tonto National Forest

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition. Possible biohazard-human waste. remote location

## UNSUITABLE PROPERTIES

## BUILDING

## CALIFORNIA

Facility 3555  
7000 East Avenue  
Livermore CA 94551  
Landholding Agency: DOE-NNSA  
Property Number: 42202020001  
Status: Excess

## Reasons:

National Security Concerns

## Comments:

Located in a National Security Complex; no public access.

## SOUTH CAROLINA

Chattooga River Cabin  
119 Beaver Lane  
Mountain Rest SC 29664  
Landholding Agency: USDA  
Property Number: 15202020011  
Status: Excess

## Directions:

Tract 0.282

## Reasons:

Floodway  
Structural Damage - Extensive Deterioration  
Documented Deficiencies-Contamination

## Comments:

Property located in floodplain, extensive deterioration; roof leaks; flooding; building unsafe; contamination; asbestos, mold; vermin; contains CFC; accessible by river.

## UNSUITABLE PROPERTIES

## LAND

## CALIFORNIA

Facility 3555

7000 East Avenue

Livermore CA 94551

Landholding Agency: DOE

Property Number: 41202020001

Status: Excess

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

---

**Summary for UNSUITABLE PROPERTIES**

Total number of = 31

---

**SUMMARY OF ALL PROPERTIES**

Suitable/Available = 1

Suitable/Unavailable = 1

Suitable/To Be = 0

\*\* Suitable/ Undefined = 0

Total Suitable = 2

Total Unsuitable = 31

Total number of = 33

Properties = 0